



THE PIPELINE ENGINEERS AND ASSOCIATES LIMITED

HES ALERT

Title :	Incident Report	Incident Date:	27 October 2016, 15:30
Alert Category :	First Aid	Reporting Date:	27 October
Protect Name :	450MW CAPP TR- North, Ashugonj	Client :	Tecnicas Reunidas (TR)

01. Description

There were some reinstatement work performed with the Maintenance Team. When one (Helper) person was hammering on a valve opposite to another Grinder was standing on line of fire. Suddenly one seam plate got out from valve and hit the lip. Immediately they stopped the work and take out injured person from work location and provide First Aid Treatment.

02. Findings and picture

- Ignoring the safe work procedure during this work time.
- Less of supervision by supervisor.
- Risk assessment was not conducted properly.
- Face shield was not being used during work time who were standing line of fire.



03. Lesson Learn

- All work should be followed safe work procedure.
- Pre job safety meeting should be conducted properly
- Ensure risk assessment are completed by supervisor before starting the work.
- Ensure the proper Personal Protective Equipment (PPE).

04. Taken Action

- Immediately stopped the job and taken the injured persons to site medical.
- Conducted the safety stand down meeting for sharing incident.
- Reviewed risk assessment for hammering job.
- Provided training for specific Job Safety Analysis.
- Provided training to all supervisor to improve more supervision workers.
- Discussed in toolbox meeting for all the construction site.