


# LESSON LEARNT



PREPARED BY: Corporate QHSE Dept.

N° 01/2022 Date: January 2022

OBJECT SICIM GOLDEN RULE # 1 - LINE OF FIRE


**We are glad to introduce the SICIM GOLDEN RULES program!**

The 12 HSE golden rules will be available on company web site and Future Inside Tool app in five languages: Italian, English, Spanish, Arabic and Kazakh.

Golden Rules will be initially released one per week, to ensure adequate focus on each rule.

Follow us in this “12 weeks trip” to a healthier and safer job!

**The first golden rule is about the line of fire risks.**



## SICIM Golden Rule #01 LINE OF FIRE

*“I will stay away out of line of fire”*

*Definition: Line of fire is that dangerous working zone around a heavy equipment, in between two pipes or pipe and heavy equipment, close to pressurized valves or get in contact to live electric energy, where the risk is extremely high with severe consequence.*

Let's give some precaution measures that must be followed:

- Do not walk or stand under a suspended load or between pipe and heavy machine.
- Be aware and stay clear of pipes under tension and of tensioned chain, sling and rope.
- Secure rolling pipes and objects.
- Never expose yourself during the maneuver of compressed cylinders.
- During the maneuver of fitting, do not expose any part of the body to the fitting, stand aside by extending the arm.
- Keep eye contact with the operator prior to approaching equipment.
- Never stand in between two pipes during cutting/fit-up operation.
- Do not stand in front of the external hydraulic clamp; stay aside.

Scan here to watch the video



[www.sicim.eu/sgr](http://www.sicim.eu/sgr)



### RECEPTION BY THE PROJECT

WHICH ACTIONS IDENTIFIED TO BE IMPLEMENTED IN THE PROJECT:

Project Manager:

Signature:

HSE Project Manager:

Signature: