

Type of Incident: Traffic

Date: 01.09.2017

Time: 17. 24, Local Time

Location: YANAO, Yamal Region, temporary vehicle site near Northern accommodation camp.

Short description of incident:

A driver started driving backwards his dump truck at the vehicle stop area near accommodation camp. It was getting dark, his dump truck was not equipped with a back-up beeper and no flag man assisted him. He did not get assured that his movement was safe and ran over another driver who was standing in front of his dump truck cabin. As a result the injured man was sandwiched between the dump truck body of the moving vehicle and stationary cabin of another vehicle. Emergency doctors failed to help him and he died.



The reasons that caused this fatality incident;

1. Traffic rules violation (Item 8.12 TR of RF “ Backing run”).
2. The vehicle not equipped with a back-up beeper.