

Workshop: Preventing Catastrophic Losses

LWDI: Leg injury caused during truck loading activities

- The contractor tried to lift three augers at the same time with a gripper to put them on the truck. One of the augers slipped out of the gripper while the contractor was standing on the loading area of the truck for a better view. He received a cut on his right leg and a fractured toe.
- First-aid in-situ and transport to the hospital.
- Instruction for employees regarding correct behaviour for lifting tasks, load casting on, risk areas and load securing have been carried out.

